Postfach 801140 · D-70511 Stuttgart



PRÜFZEUGNIS (Test Certificate)

900 6806 021/PZ-9-396/E *)

Auftraggeber: (Client)

Akzo Nobel Hilden GmbH Düsseldorfer Straße 96-100

40721 Hilden

Betreff: Subject Reaction to fire testing according to DIN 4102-1, "Baustoffklasse B1"

Prüfmaterial: (Test Material)

Colourless 1-component / 2-component polyurethane varnish

"Aqualit clear stair varnish A-ST260-xx1"

on flame-retardant (DIN 4102-B1) particleboard – also veneered – as a flame-retardant building material ("Baustoffklasse DIN 4102-B1")

Datum: (Date) Gültigkeitsdar 15th of November 2021

Gültigkeitsdauer: (Period of Validity)

until 30th of June 2025

Hinweis: (Notes)

If the above-mentioned building material is not used as a building product according to MBO § 2, Para. 10, an "allgemeines bauaufsichtliches Prüfzeugnis (abP)" is not required.

This test certificate does not apply if the tested building material is used as a building product within the meaning of the building regulations of the federal states (MBO § 17, Para. 1).

This test certificate does not replace a possibly necessary certification according to German building regulations.

This test certificate can serve as a basis in the building supervisory procedure:

- in the case of regulated building products for the required certificates of conformity
- in the case of non-regulated building products, for the required proof of usability.

The explanations in DIN 4102-1, Annex D, in particular on third-party inspection, are to be particularly observed.

*) This test certificate is the English version of our test certificate 900 6806 021/PZ-9-396 dated 23th of June 2021. In cases of doubt, the German version applies.

This test certificate comprises 6 pages of text and 3 annexes. The text pages and annexes bear our official seal. Reproduction and publication of the test certificate, both in full and in abridged form, as well as use for advertising purposes is only permitted with the written consent of MPA Universital Stuttgart. The test certificate is issued without prejudice to the rights of third parties, in particular private property rights. The place of jurisdiction and performance is Stuttgart.

Materialprüfungsanstalt Universität Stuttgart Pfaffenwaldring 32 D-70569 Stuttgart (Vaihingen) USt.-ID-Nr. DE 147794196

Telefon: (0711) 685 - 0 Telefax: (0711) 685 - 62635 Internet: www.mpa.uni-stuttgart.de BW-Bank Stuttgart / LBBW Konto-Nr. 7 871 521 687 BLZ 600 501 01 IBAN: DE51 6005 0101 7871 5216 87 BIC/SWIFT-Code: SOLADESTXXX

¹ The "xx" as part of the product name is replaced by numbers representing the different grades of gloss of the varnish system

Prüfzeugnis (Test Report) No.: 900 6806 021/PZ-9-396/E

page 2 of 6 text pages

dated 15. November 2021

1. Material description

Colourless 1-component / 2-component polyurethane varnish "Aqualit A-ST260xx" in the gloss levels matt (A-ST260-10) and silk matt (A-ST260-20), applied on flame-retardant (DIN 4102-B1) particle boards - also with veneer.

The 2-component polyurethane varnish "A-ST260-xx" has to be used with the hardener "HWA6000".

Application rate (wet):

varnish: 3 x 120 g/m²

Mixing ratio (by weight):

varnish: hardener = 20:1

Type of application:

Compressed air spraying

Field of application:

Interior fittings

Trade name:

"Aqualit A-ST260-xx" hardener "HWA6000"

Receipt of samples:

- a) 24th of October 2017 (receipt-No. 17/324)
- b) 27th of November 2018 (receipt-No. 18/375)
- c) 10th June 2020 (receipt-No. 20/136)

Quantity:

- a) 4 flame-retardant particle boards (DIN 4102-B1), coated with "A-ST260-10"
- b) 4 flame-retardant particle boards (DIN 4102-B1), coated with "A-ST260-20"
- c) 4 flame-retardant particle boards (DIN 4102-B1), coated with "A-ST260-10"

2. Sample preparation

Test specimen made of fire-retardant (DIN 4102-B1) particle boards, 1000 mm x 190 mm x 12 mm, were coated on one side with the paint system in the presence of an employee of the MPA Stuttgart at the company headquarters in Hilden. The carrier boards were provided by the MPA in each case.

For the B2 tests, 190 mm x 90 mm samples were cut from the coated particleboard test specimen.

Prüfzeugnis (Test Report) No.: 900 6806 021/PZ-9-396/E

page 3 of 6 text pages

dated 15. November 2021

3. Test procedure

The tests were carried out according to DIN 4102-1:1998 and DIN 4102-16:2015 in the fire shaft according to DIN 4102-15:1990 and the approval principles for the proof of the low flammability of building materials (version August 1994), published by the "Deutsches Institut für Bautechnik (DIBt)" in Berlin.

4. Test results

4.1 Test according to DIN 4102, clause 6.2, "Baustoffklasse B2"

Material	a)							
Specimen-No.:	1	2	3	4	5			
Max. flame height within 20 s	4	4	4	4	4			
Burning Droplets	none	none	none	none	none			

Material	b)					
Specimen-No.:	1	2	3	4	5	
Max. flame height within 20 s	5	5	5	5	5	
Burning Droplets	none	none	none	none	none	

Material	¥0	с)							
Specimen-No.:	1	2	3	4	5				
Max. flame height within 20 s	4	4	3	3	4				
Burning Droplets	none	none	none	none	none				



Prüfzeugnis (Test Report) No.: 900 6806 021/PZ-9-396/E

page 4 of 6 text pages

dated 15. November 2021

4.2. Test according to DIN 4102, clause 6.1 - "Baustoffklasse B1"

The fire shaft test ("Brandschacht") A, B, C on the samples a), b), c) were carried out on free-hanging specimens without any substrates.

4.2.1. Results of fire shaft tests ("Brandschacht") (part 1)

			Test	Resulte	of Specin	nen Asse	mbly
Line	No.		A	B	C Specifi	nen Asse	indiy E
1	No. of fastening method		/ /				
	according to DIN 4102-15, table 1		7	7	7	7	7
2	Max. flame height		100,0				,
-	above the lower edge of the sample	cm	90-100	80-90	80-90	_	_
3	Time of appearance 1)	min:s	1:45	1:25	1:20		_
					1.20	S.WX	
4	Occurrence of holes in the material						
-540	Time of appearance 1)	min:s	7-	_	_	_	
	Time of appearance	111111.0	48.75				
5	Observations of the reverse face of the specimen				0		
	Flames / Glowing	1900					
	Time of appearance 1)	min:s		-	-	-	
6	Discolouring						
-	Time of appearance 1)	min:s	\ -		-	-	-
7	Burning droplets						
	Beginning 1)	min:s	-	-	-	- 	
	Continued burning on sieve tray	S					
8	Sporadically dripping sample material		-	-	-		->
9	Steady dripping sample material		25.	-	-	-	
10	Burning dripping sample parts		2				
10	Beginning 1)	min:s					
	Amount:	111111.5	-		1 -	-	
11	Sporadically dripping sample material		12		_	_	-
12	Steady dripping sample material		-	_	_	-	
	closely stipping campio material		2 22				
13	Duration of continued burning on the						
	sieve bottom (max.)	min:s	1-	-	-	_	_
14	Impairment of the burner flame due to						
	dripping/falling material						
	Time of appearance 1)	min:s	υ	_	-	-	4
	Premature end of experiment		2				
15	End of fire reaction					8 4	8.7
	on the specimen 1)	min:s	·= :	-	-	, - · ·	170
16	Time of premature finishing the test,	2007			15	Deliver,	EJ E
	if done so 1)	min:s	2	-	-!	- 1 po	37 - 31

¹⁾ Elapsed time from the start of the test (t=0) shall be recorded

page 5 of 6 text pages

dated 15. November 2021

4.2.2 Results of fire shaft tests ("Brandschacht") (part 2)

11,	n	Test Results of Specimen Assembly					
Line	No.		Α	В	С	D	E
	Afterburning after the end of the test						
17	Duration	min:s	-		-	00 553	-
18	Number of specimen			-3			
19	On front face of the specimen						
20	On reverse face of the specimen						
21	Flame height	cm		-	-		-
	Afternlaw after and of test			4			
22	Afterglow after end of test Duration	minia					
		min:s	y 5 5 5	/=	-	-	-
23	Number of specimen						
0.4	Location of glowing						
24	Lower half of the specimen						
25	Upper half of the specimen	14		(40)			
26	Front face of the specimen						
27	Reverse face of the specimen						
	Smoke density			2000	200		
28	≤ <u>400 % · min</u>		20	20	30		āu
29	≥ <u>400 % · min</u>		18				
1,000	(very strong smoke development)	11	3. -	0¥0	=	= -	8
30	Graph in annex No.		1	2	3		
	Residual length						
31	Single results of each specimen	cm	24 25	24 25	26 26	ā	=
		× =	25 24	24 28	25 24	-	-
32	Average of each specimen assembly	cm	25 *)	25 *)	25 *)	2	-
33	Photo of the test assembly						
	in annex No.		- :	-	-		-
70.00	Flue gas temperature		21.000				
34	Maximum of the average value	°C	139	137	129	-	
35	Time of appearance 1)	min:s	4:26	4:28	4:41	-	_
36	Graph in annex No.	5717-2716-2716-2	1	2	3	-	-
37	Notes:		Residual I	ength of th	е		
31	1) Elegand time from the start of the tea		non coate		board: *) 24	cm	

¹⁾ Elapsed time from the start of the test (t=0) shall be recorded

5. Classification

All tested samples met the requirements for building materials according to DIN 4102-1, clause 6.1.2.2 and clause 6.2 for class B2.

Thus, the product as described in section 1 meets the requirements for building materials according to class B1 of DIN 4102-1:1998.

No sample parts fell off during the test according to DIN 4102-1:1998, clause 6.2.5 and according to DIN 4102-16:2015 neither burning nor glowing.

According to DIN 4102-16:2015, clause 9.3, the material is considered to be non-molten-dripping.

Prüfzeugnis (Test Report) No.: 900 6806 021/PZ-9-396/E

page 6 of 6 text pages

dated 15. November 2021

6. Notes

6.1 The containers of the 1-component / 2-component varnish must be labelled according to DIN 4102-1, clause 7 with the following marking:

DIN 4102 – B1, aufgebracht auf schwerentflammbaren (DIN 4102-B1) Holzspanplatten

6.2 The assessment in section 5 only applies to the 1-component / 2-component varnish described in section 1 and tested as in section 3, applied to flame-retardant (DIN 4101-B1) particleboard - also veneered.

Used in connection with other materials its fire performance is likely to be influenced this negatively, that the given classification in section 5 is no longer valid.

Fire performance in connection with other materials is to be tested and classified separately.

- 6.3 For outdoor use, DIN 4102-16: 2015, clause 6.2 requires proof that the requirements for building materials of building material class B1 "schwerentflammbar" (flame-retardant) are met even after 2 and 5 years of outdoor weathering. This proof has not (yet) been provided.
- 6.4 The validity of the assessment in section 5 of this test certificate ends on 30th of June 2025 The period of validity may be extended upon application. Verification testing is necessary for this purpose.
- 6.5 This test certificate does not replace an "allgemeines bauaufsichtliches Prüfzeugnis (abP)" or an "allgemeine bauaufsichtliche Zulassung (abZ)" that may be required.

Abteilung Brandschutz / Fire Safety Department
Referat Brandverhalten von Baustoffen / Section Reaction to Fire


Der Prüfingenieur
The Engineer in Charge

Die Leiterin der Prüfstelle Head of Notified Fire Testing Centre

Dipl.-Ing. Ernst Willand

Dipl.-Ing. Sabrina Heldele-Twietmeyer

Annex 1, dated 15. November 2021




max. Rauchgastemp. 139 °C
erreicht nach 4:26 min:sec
max. Rauchdichte 6 %
Integralwert 20 %*min

Figure 1: Results of fire shaft test A ("Brandschachtversuch") (smoke density, flue gas temperature)




Annex 2, dated 15. November 2021



max. Rauchgastemp. 137 °C
erreicht nach 4:28 min:sec
max. Rauchdichte 5 %
Integralwert 20 %*min

Figure 2: Results of fire shaft test B ("Brandschachtversuch") (smoke density, flue gas temperature)



max. Rauchgastemp. 129 °C
erreicht nach 4:41 min:sec
max. Rauchdichte 9 %
Integralwert 30 %*min

Figure 3: Results of fire shaft test C ("Brandschachtversuch") (smoke density, flue gas temperature)

